	TypeL	1	#Hits	Search Text	DBs	Time Stamp	Stamp Comments	Error Definition	Errors
Н	BRS		54	(toilet near10 evacuat\$3) same level	USPAT; US-PGPUB;2004/ EPO; JPO;06:17 DERWENT	2004/09/30 06:17			0
, ,	BRS	1.2	. 9	Ll and (reduc\$3 near8 level)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/09/30 06:19			0
Э	BRS	3 F	202	toilet same (reduc\$3 near8 level)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/09/30 06:34			0
4	BRS	L6	09	L3 and (addi\$7 near5 (water or fluid or liquid))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/09/30 06:25			0
5	BRS	L7	50	L3 and (addi\$7 adj5 (water or liquid))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/09/30 06:26			0
9	BRS	L8	7580	7580 toilet same cleaning	USPAT; US-PGPUB;20 EPO; JPO;06	2004/09/30 06:34			0
7	BRS	L9	204	L8 and (reduc\$3 near8 level)	USPAT; US-PGPUB; EPO; JPO; DERWENT	USPAT; US-PGPUB;2004/09/30 EPO; JPO;07:04 DERWENT			0
8	BRS	L10	692	L8 and brush\$3	USPAT; US-PGPUB;2004/09 EPO; JPO;07:04 DERWENT	2004/09/30 07:04			0
6	BRS	L111	м	L10 and (reduc\$3 near8 level)	USPAT; US-PGPUB;2004/0 EPO; JPO;07:05 DERWENT	2004/09/30 07:05			0